



Stepper Motor 010




Gear Box



Gear 1 is attached directly to the shaft of the motor. 48 steps will turn this 1 time.

Gear 2 & 3 (pulled out slightly in the picture to the left). Gear 2 is driven by gear 1 on the “top” end and meshes with gear 3 on the “bottom” end. Gear 3 is driven by gear 2 on the top end and meshes with gear 4 on the bottom end.

Gear 4 is connected to the shaft in which the wheel of the winch is attached.



WINCH

